

Certificate of Fitness

S993

Plate: S993
 1993 DOMETT RSKF2F2E 8.5 RED
 Owner: MIKAELE SONE MASOE17/08/1993
 Class: TD
 Fuel:
 ODO Reading: (K)
 Last Inspection: PASSED

Inspection Expiry: 22/08/2018
 Insp. Freq. (months): 6

VIN Location: No of Axles: 4
 Last Hubo Serial No : 2/555330

Reg Expiry	16/11/2018
AVIC No.	VT135
Order Number	
WoF/CoF Fee \$	
Receipt Number	8694960
Odometer Reading	
Hubo Reading	87900
Hubo Number	2/555330
Recheck Fee \$	
Recheck Odo	
Recheck Hubo	
Tractor/Trailer Reg No.	DCZ209
TSL	0218466
Tare	
Air System	
Max Air Pressure	
Appns/ Pressure	
Recovery Time	
Auxiliary Device	
Warning Device	

VIN/Chassis No	5608	Product Code	POS	LATIS	ISS
Initial Inspection	Fail	Lane No.	Recheck Inspection	Lane No.	NZTA Auth No.
Inspector ID	WAVN	2	Inspector ID		Label No.
Insp. sign	AN	Date	28/06/2018	Insp. sign	Date
NZ Standards 5413 <input type="checkbox"/> 5444 <input type="checkbox"/> 5446 <input type="checkbox"/> 5450 <input type="checkbox"/> 5451 <input type="checkbox"/> 5467 <input type="checkbox"/> NZHVBC <input type="checkbox"/> Other <input type="checkbox"/>					
Checklist:	CHTR Rev 3	This check sheet does not constitute a Warrant of Fitness or Certificate of Fitness. Rechecks must take place within 28 days of the original inspection. After the 28 days a new inspection must be carried out and a new fee paid. Last date for recheck is 26/07/2018			
Detailed checklist available to customer on request					

WRV	Tyre Tread	WAVN Service Brake						WAVN Park Brake				Air System	
		Initial 82 %			Recheck % or Static P/F			Initial 41 %		Recheck % or Static P/F			
Axle	L	R	Left/Weight	Right %	Max % Imbalance	Left/Weight	Right %	Max % Imbalance	Left/Weight	Right %	Left/Weight	Right %	
1	6	6	4500	79	9								Max Air Pressure
2	8	10	4550	79	8								Appns/ Pressure
3	3	3	4500	95	5				4500	91			Recovery Time
4	12	12	4500	77	20				4500	79			Auxiliary Device
5													Warning Device

Category Description	Pass/Fail	Inspector ID	Fault Code	Reasons Vehicle Failed Its Inspection
Lighting	Pass	TGR1	UXA4	Left Wheel Hub Binding Axle 1
Vehicle Raised	Fail	TJR1	ELS1	Middle Load Anchorage Twist Lock Cracked As Marked - <i>Moan</i>
Exterior	Fail	TJR1	EWI4	Left Load Rated Curtain System Torn All
Underbody	Fail	WRN5	EBN2	Front Body/Panels Corrosion As Marked
			CRN2	Front Chassis Rails Corrosion As Marked
			BLI2	Axle 1 Brake Linings Low All
			BLI1	Axle 2 Brake Linings Low Left
			BAW2	Axle 1 Slack Adjusters Play All
			BAW1	Axle 2 Slack Adjusters Play Left
			EAN2	Axle 1 Sub Frame Structure Corrosion Rear
EAN3	Axle 3 Sub Frame Structure Corrosion As Marked			

AXLES 3 SCAM play Right

Notes

All Chassis Rail Outer Rust Developing

All Chassis Rust Developing Requires Attention Soon

All Tyre Tread Low