


Report ID: 17,405,755

Version:

Created: 22 Mar 2018

Make:	Holden	Model:	Cruze	Body Style:	Hatchback
Year:	2,016	Registration:	KDK778	Reg Expiry:	12 Apr 2018
WoF Expiry:		Odometer:	43,725 Kms	Good No:	17405755
VIN:	6G1PD6EM8GL244839	Next Service:	45000	Service History	<b>/:</b> Yes



Interior Comments					
Seats	Good				
Carpets	Poor				
Panels	Good				
Dashboard	Good				

Evidence of Cam Belt Replacement: No

I have read and understood this condition guide.

Inspected by: Brian Hill

	'						
	Sat. Nav. (basic test only)	~					
Kms:	Reversing camera	V					
	Date: 22 Mar 2018	Date: 22 Mar 2018					
Name:	Signature:						

V	lake:	Holden	Model:	Cruze	<b>Body Style:</b>	Hatchback			Pass	Fail	N/A
Υ	ear:	2,016	Registration:	KDK778	Reg Expiry:	12 Apr 2018		Engine			
W	oF Expiry:		Odometer:	43,725 Kms	Good No:	17405755		Oil level	~		
٧	IN:	6G1PD6EM8GL244839	Next Service:	45000	Service Histor	y: Yes		Smoke & fumes	~		
_							5	Performance	~		
		port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	· heen dismantled or		Noise	~		
С	liagnostic te	sting undertaken. The v	vehicle has beer	driven up to 50km/h	from cold. The	Vendor recommends		Cooling System			
а	full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	charge.		Coolant condition	~		
					7		٦	Performance	~		
ł	(ey:		$-\infty$		-00-			Radiator / Hoses (visual)	~		
	= scratch	No.				- M		Transmission			
	= dent	sc 6/6				BIII _	]	Operation	~		
	= rust T = paint defe	7110				JUIA		Noise	~		
	= crack		_		-			Clutch	· ·		
	= pin dent						Ш	CV joints	~		
*	= decals	sc 6/6				EIIP s	Ш	Wheel bearings	<b>'</b>		
S	C = stone chi	ps V					1		•		
W	/ = significan	t scuffs W			-W-			Brakes			
								Performance	<b>/</b>		
	Body Insp	<u>section Comments</u>	Note: som	ne defects & blemishes	may not be disp	played in the diagram		Hand Brake	<b>/</b>		
	Glovebox b	roken. Stone chips front	t screen. Rear do	or glasses not working				Tyres (lowest observed tread	l depth	of tyre	es) 
								Left front	3	3	mm
								Right front	13.	3	mm
							ᆜᅵ	Left rear	***	3	mm
	Condition	ns During Body Insp	pection:	Wet				Right rear	4	1	mm
							7	Spare		Yes	
	<u>Under Ca</u>	rriage & Under Bon	net Inspection	on Comments				Suspension			
	Good.							Suspension performance	>		
								Steering performance	~		
								Shock absorbers	>		
								Air Conditioning / Heater			
							7	Operation	~		
	Interior C	<u>omments</u>						Electrical / Accessories			
	Seats	Good						Head lights	<b>'</b>		
		Poor						Tail lights	V		
	Carpets	1,001						Indicators	~		
	Panels	Good						Dashboard warning lights	~		
								Wipers (front & rear)	<b>V</b>		
	Dashboa	rd Good						Window winder FL	· ·		
_							╝	Window winder FR	<b>V</b>		
	General C	Comments						Window winder RL		<b>/</b>	
	Runs well.							Window winder RR		~	
										_	
								Rear view mirrors		<b>&gt;</b>	
								Radio (basic test only)	<b>/</b>		
								CD (basic test only)	~		
							_	Number of keys	2		ı
	Road Con	ditions During Test	Drive:	Wet			_[	Central locking	~		
	Engine Ti-	ming Mechanism:	C. 1.1				٦	Remote locking	~		
	Lilgine III	ming wiechanism:	Cambelt	τ				Sat. Nav. (basic test only)			~
	E. J. J.	of Cam Polt Poplace		_	Kmc.		- 1 '				1