

**General Comments** 

## **Turners Certified Imports 50 Point Check**

Report ID: 17,483,234

Version: 2

Created: 05 Oct 2018

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.


	IMPORTI	ED VEHICLES	accredited insp	ection agency and been i	.est	driven up to	) SUKITI,
	Make:	Subaru	Body Style:	Hatchback		Seats:	Good
	Model: Year:	Impreza 2007	Odometer: VIN:	78,961 Kms 7AT0GF09X18004697		Carpets:	Good
[	Under	]	Panels:	Good			
		-				Dashboard:	Good


Panels:	Good	
Dashboard:	Good	
Engine Timi	ng Mechanism:	Cambelt
Evidence of	Cam Belt Replacement:	No
Replaced At	(odometer reading):	

Dry

Tyres (lowest observed tread







**Road Conditions During Test Drive:** 

