

Turners Certified Imports 50 Point Check

Report ID: 17,484,430

Version: 3

Created: 01 Nov 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

Make: Subaru Body Style: Wagon Model: Exiga Odometer: 124,162 Kms	
Year: 2009 VIN: 7AT0GF1RX18012594 Carpets: Good Under Carriage & Under Bonnet Inspection Comments Good Panels: Good	
Dashboard: Good Engine Timing Mechanism: Cambelt	
General Comments Evidence of Cam Belt Replacement: Yes Replaced At (odometer reading): 101,180 Road Conditions During Test Drive: Wet	
Electrical Transmission & Drive Engine Tyres (lowest observed to depth)	read
	7.0 mm
	7.0 mm
Tail lights Clutch Performance Left rear	7.0 mm
	7.0 mm
Cooling System	'es
Wipers (front & rear) Wheel balance Coolant condition Tools	
Window winder FL Brakes Performance Interior	
Window winder FR Performance Radiator / Hoses (visual) AC Operation	
Window winder RL Window winder RR Hand Brake Suspension Seatbelts	

•

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Reversing camera

Keys & Locking

Central locking

Remote locking

Number of keys

3

Suspension performance

Steering performance

Inspected by: Jason Law

Shock absorbers

Date: 05 Oct 2018

X = Fail = Not applicable for this vehicle

Horn

Turners Certified Key

✓ = Pass