

Turners Certified Imports 50 Point Check

Report ID: 17,651,138

Version:

Created: 17 Jan 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Mazda Make: **Body Style: Hatchback** Odometer: 109,601 Kms Demio Model: 7AT0C12HX18198026 2009 VIN: Year:

Under Carriage & Under Bonnet Inspection Comments

OK.

General Comments

Good little hatch.

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Timing Chain **Engine Timing Mechanism:**

Not Applicable **Evidence of Cam Belt Replacement:**

Replaced At (odometer reading):

Road Conditions During Test Drive:

Dry

Electrical		
Battery		
Head lights		
Tail lights		
Indicators		
Dashboard warning lights		
Wipers (front & rear)		
Window winder FL	V	
Window winder FR	V	
Window winder RL	V	
Window winder RR	V	
Rear view mirrors	V	
Radio (basic test only)		
CD (basic test only)		
Reversing camera	•	





