

## **Turners Certified Imports 50 Point Check**

 Report ID:
 17,651,313

 Version:
 2

 Created:
 07 Jan 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Mazda	Body Style:	Sedan	
Model:	Atenza	Odometer:	75,809 Kms	
Year:	2008	VIN:	7AT0C139X18101722	

<u>Under Carriage & Under Bonnet Inspection Comments</u> Tidy.

## General Comments

Nice tidy car.

	Seats:	Good		
	Carpets:	Good		
	Panels:	Good		
	Dashboard:	Good		
	Engine Timing Mechanism:		Timing Chain	
	Evidence of Cam Belt Replacement:		Not Applicable	

Dry

Replaced At (odometer reading):

Road Conditions During Test Drive:

Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)
Battery	Operation	Oil level	Left front 6 mm
Head lights	Noise	Smoke & fumes	Right front 6 mm
Tail lights	Clutch	Performance	Left rear 7 mm
Indicators	CV joints	Noise	Right rear 7 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	<ul> <li>Turners Certified Key</li> <li>✓ = Pass X = Fail</li> <li>● = Not applicable for this vehicle</li> </ul>
Reversing camera •	Number of keys 2	Inspected by: Daryll Timms	Date: 07 Jan 2019

Name: .....

Signature: .....