

Turners Certified Imports 50 Point Check

 Report ID:
 17,652,329

 Version:
 1

 Created:
 17 Jan 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Honda	Body Style:	Hatchback
Model:	FIT	Odometer:	44,042 Kms
Year:	2013	VIN:	7AT08G2YX18241191

<u>Under Carriage & Under Bonnet Inspection Comments</u> Tidy.

General Comments

Nice little hatch.

Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
Engine Timing Mechanism:		Timing Chain
Evidence of	Cam Belt Replacement:	Not Applicable

Dry

Road Conditions During Test Drive:

Replaced At (odometer reading):

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)	
Battery	Operation	Oil level	Left front 6 mm	
Head lights	Noise	Smoke & fumes	Right front 7 mm	
Tail lights	Clutch	Performance	Left rear 3 mm	
Indicators	CV joints	Noise	Right rear 3 mm	
Dashboard warning lights	Wheel bearings	Cooling System	Spare No	
Wipers (front & rear)	Wheel balance		Tools	
Window winder FL	Brakes	Coolant condition	Interior	
Window winder FR		Performance		
Window winder RL	Performance	Radiator / Hoses (visual)	AC Operation	
Window winder RR	Hand Brake	Suspension	Heater fan	
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts	
Radio (basic test only)	Central locking	Steering performance	Horn	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓= PassX= Fail●= Not applicable for this vehicle	
Reversing camera •	Number of keys 2	Inspected by: Daryll Timms	Date: 17 Jan 2019	

Signature: