

## **Turners Certified Imports 50 Point Check**

Report ID: 17,668,984

Version: 1

28 Jan 2019 Created:

## **Note: This report is not a warranty**


This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.


Mazda **Body Style: SUV** Make: Odometer: 58,849 Kms CX-5 Model: 2013 7AT0C144X19116074 VIN: Year: **Under Carriage & Under Bonnet Inspection Comments** Tidy. **General Comments** Tidy SUV. **Electrical Transmission & Drive Engine Battery** Operation Oil level **Head lights** Noise Smoke & fumes Tail lights Clutch Performance


Engine Timing Mechanism:		Timing Chain
Dashboard:	Good	
Panels:	Good	
Carpets:	Good	
Seats:	Good	

Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading): Dry **Road Conditions During Test Drive:** Tyres (lowest observed tread









= Not applicable for this vehicle