

Turners Certified Imports 50 Point Check

 Report ID:
 17,670,985

 Version:
 1

 Created:
 04 Feb 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Mazda	Body Style:	SUV
Model:	MPV	Odometer:	121,924 Kms
Year:	2008	VIN:	7AT0C11EX19203029

<u>Under Carriage & Under Bonnet Inspection Comments</u> Tidy.

General Comments

Nice 8 seater people mover.

Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
Engine Timing Mechanism:		Timing Chain
Evidence of Cam Belt Replacement:		Not Applicable

Dry

Road Conditions During Test Drive:

Replaced At (odometer reading):

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 5 mm
Head lights	Noise	Smoke & fumes	Right front 5 mm
Tail lights	Clutch	Performance	Left rear 5 mm
Indicators	CV joints	Noise	Right rear 5 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare No
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓=PassX=Fail•=Not applicable for this vehicle
Reversing camera •	Number of keys 2	Inspected by: Daryll Timms	Date: 04 Feb 2019

Name:

Signature: