

## **Turners Certified Imports 50 Point Check**

Report ID: 17,672,732

Version:

Created: 20 Feb 2019

## **Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Honda Make: **Body Style: Hatchback** FIT Odometer: 94,509 Kms Model: 2013 7AT08G2YX19006116 VIN: Year:

**Under Carriage & Under Bonnet Inspection Comments** Tidy.

**General Comments** 


Smooth, quiet hatch.


Good Seats: Good Carpets: Good Panels: Dashboard: Good

Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading):


Dry **Road Conditions During Test Drive:** 

Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	•





Inspected by: Daryll Timms



Date: 20 Feb 2019