

Turners Certified Imports 50 Point Check

Report ID: 17,672,848

Version:

12 Feb 2019 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Toyota **Body Style: Wagon** Corolla Odometer: 121,255 Kms Model: 2013 7AT0H607X19017515 VIN: Year:


Under Carriage & Under Bonnet Inspection Comments Tidy.


General Comments


Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:** Tidy wagon. Replaced At (odometer reading): Dry **Road Conditions During Test Drive:** Tyres (lowest observed tread **Transmission & Drive Engine** depth)

Electrical Battery Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Reversing camera •







		= Not applicable for this vehicle			
nspected by:	Daryll Timms		Date:	12 Feb 2019	