

Turners Certified Imports 50 Point Check

Report ID: 17,715,025

Version:

15 May 2019 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Mazda Make: **Body Style: SUV** CX-7 Odometer: 91,764 Kms Model: 2008 7AT0C13PX19106436 VIN: Year:

Under Carriage & Under Bonnet Inspection Comments Tidy.

General Comments Tidv 2WD SUV.

Good Seats: Good Carpets: Good Panels: Dashboard: Good

Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading): Dry

Electrical Battery Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)

Transmission & Drive Operation Noise Clutch **CV** joints Wheel bearings Wheel balance **Brakes** Performance **Hand Brake Keys & Locking** Central locking Remote locking 1 Number of keys

Engine Oil level Smoke & fumes Performance Noise **Cooling System** Coolant condition Performance Radiator / Hoses (visual) **Suspension** Suspension performance Steering performance Shock absorbers

Road Conditions During Test Drive:

depth) mm 6 Left front 6 mm Right front 6 Left rear mm 6 Right rear Yes Spare **Tools Interior AC Operation** Heater fan Seatbelts Horn **Turners Certified Key X** = Fail ✓ = Pass

Tyres (lowest observed tread

Inspected by: Daryll Timms Date: 15 May 2019

Reversing camera

= Not applicable for this vehicle