

Turners Certified Imports 50 Point Check

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Honda	Body Style:	Hatchback
Model:	FIT	Odometer:	78,941 Kms
Year:	2013	VIN:	7AT08G2YX19002546

Under Carriage & Under Bonnet Inspection Comments Tidy.

General Comments

Nice tidy hatch.

Seats:	Good			
Carpets:	Good			
Panels:	Good			
Dashboa	_{rd:} Good			
Engine T	iming Mechanism:	Timing Chain		
Fvidence	of Cam Belt Replacement	Not Applicable		

Dry

Evidence of Cam Belt Replacement:

Replaced At (odometer reading):

Road Conditions During Test Drive:

Electrical		Transmission & Drive		Engine		Tyres (lowest observed tread depth)		
Battery		Operation		Oil level		Left front	б	mm
Head lights		Noise		Smoke & fumes		Right front	6	mm
Tail lights		Clutch	•	Performance		Left rear	4	mm
Indicators		CV joints		Noise		Right rear	4	mm
Dashboard warning lights		Wheel bearings		Cooling System		Spare	No	
Wipers (front & rear)		Wheel balance		Coolant condition		Tools	V	,
Window winder FL		Brakes		Performance		Interior		
Window winder FR		Performance		Radiator / Hoses (visual)		AC Operation		
Window winder RL		Hand Brake		Radiator / Hoses (Visual)		Heater fan		
Window winder RR		напо втаке		Suspension		Seatbelts		
Rear view mirrors		Keys & Locking		Suspension performance				
Radio (basic test only)		Central locking		Steering performance		Horn		
CD (basic test only)		Remote locking		Shock absorbers		Turners Certified Ke ✓ = Pass • = Not applicabl	🗙 = Fail	hicle
Reversing camera	•	Number of keys	1	Inspected by: Daryll Timn	ns	Date: 15		

Signature: