

Turners Certified Imports 50 Point Check

 Report ID:
 17,739,497

 Version:
 1

 Created:
 15 Feb 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Toyota	Body Style:	Hatchback
Model:	Corolla	Odometer:	123,859 Kms
Year:	2008	VIN:	7AT0H607X19038353

<u>Under Carriage & Under Bonnet Inspection Comments</u> Tidy.

Engine Timiı	ng Mechanism:	Timing Chain	
Dashboard:	Good		
Panels:	Good		
Carpets:	Good		
Seats:	Good		

Evidence of Cam Belt Replacement:

General Comments Good tidy wagon.

Replaced At (odometer reading):

nt. Not Applicable

. Dry

Road Conditions During Test Drive:

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front 7 mm
Tail lights	Clutch	Performance	Left rear 4 mm
Indicators	CV joints	Noise	Right rear 4 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓= PassX= Fail●= Not applicable for this vehicle
Reversing camera •	Number of keys 2	Inspected by: Daryll Timms	Date: 15 Feb 2019

Name:

Signature: