

## **Turners Certified Imports 50 Point Check**

Report ID: 17,739,957

Version: 1

20 Feb 2019 Created:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Suzuki Make: **Body Style: Hatchback** Swift Odometer: 115,117 Kms Model: 7AT0GK0CX19208860 2008 VIN: Year:

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy.

**General Comments** 

Tidy manual Swift sport.

Good Seats: Good Carpets: Good Panels: Dashboard: Good

Timing Chain **Engine Timing Mechanism:** 


Not Applicable **Evidence of Cam Belt Replacement:** 


Replaced At (odometer reading):


**Road Conditions During Test Drive:** 

Dry

**Electrical Battery Head lights** Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Reversing camera •







**Tyres** (lowest observed tread

Date: 20 Feb 2019