

Turners Certified Imports 50 Point Check

 Report ID:
 17,740,468

 Version:
 1

 Created:
 21 Feb 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

ſ	Make:	Honda	Body Style:	Hatchback
	Model:	FIT	Odometer:	79,826 Kms
	Year:	2011	VIN:	7AT08G2YX19515747

Under Carriage & Under Bonnet Inspection Comments Tidy

General Comments

Good little hatch.

	Seats:	Good	
	Carpets:	Good	
	Panels:	Good	
	Dashboard:	Good	
	Engine Timing Mechanism: Evidence of Cam Belt Replacement:		Timing Chain
			Not Applicable

Dry

Road Conditions During Test Drive:

Replaced At (odometer reading):

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)	
Battery	Operation	Oil level	Left front 6 mm	
Head lights	Noise	Smoke & fumes	Right front 6 mm	
Tail lights	Clutch	Performance	Left rear 6 mm	
Indicators	CV joints	Noise	Right rear 6 mm	
Dashboard warning lights	Wheel bearings	Cooling System	Spare No	
Wipers (front & rear)	Wheel balance		Tools	
Window winder FL	Brakes	Coolant condition	Interior	
Window winder FR		Performance		
Window winder RL	Performance	Radiator / Hoses (visual)	AC Operation	
Window winder RR	Hand Brake	Suspension	Heater fan	
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts	
Radio (basic test only)	Central locking	Steering performance	Horn	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✔= Pass¥= Fail●= Not applicable for this vehicle	
Reversing camera	Number of keys 2	Inspected by: Daryll Timms	Date: 21 Feb 2019	

Name: