

## **Turners Certified Imports 50 Point Check**

Report ID: 17,755,852

Version: 3

Created: 19 Sep 2018

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Subaru	Body Style:	Hatchback
Model:	Impreza	Odometer:	71,002 Kms
Year:	2008	VIN:	7AT0GF09X18013338

**Under Carriage & Under Bonnet Inspection Comments** 

General Comments

Seats:	Average
Carpets:	Good
Panels:	Average
Dashboard:	Good

Engine Timing Mechanism:


Evidence of Cam Belt Replacement:


Replaced At (odometer reading):

Road Conditions During Test Drive:

Wet

Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	•







Inspected by: Jason Law Date: 19 Sep 2018