

Turners Certified Imports 50 Point Check

Report ID: 17,756,268

Version: 1

Created: 23 Oct 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Body St	tyle: Wagon		
ocy Odome	eter: 88,930 Kms		
VIN:	7AT0C133X18122300		
Under Carriage & Under Bonnet Inspection Comments			

Dashboard:	Good		
Panels:	Good		
Carpets:	Good		
Seats:	Good		

General Comments		


Engine Timing Mechanism: Timing Chain


Evidence of Cam Belt Replacement: Not Applicable


Replaced At (odometer reading):

Road Conditions During Test Drive: Dry









Inspected by:	Xinghui Lin	Date:	22 Oct 2018