

Turners Certified Imports 50 Point Check

Report ID: 17,756,309

Version:

Created: 13 Nov 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Subaru

Body Style: Hatchback

Model: Impreza

Odometer: 120,496 Kms

Year: 2008

VIN: 7AT0GF09X18013527

Under Carriage & Under Bonnet Inspection Comments

General Comments

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism:

Evidence of Cam Belt Replacement:

Replaced At (odometer reading):


Road Conditions During Test Drive:


Cambelt


Yes

104,202

Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	•







Date: 22 Oct 2018