

## Turners Certified Imports 50 Point Check

Report ID: 17,756,487

Version:

Created: 22 Oct 2018

## **Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold

IMPORTED VEHICLES	accredited inspection a		st unveil up to Jokin/ii ii	oni cola.			
Make: Subaru Body Style: Hatchback Model: Impreza Odometer: 131,896 Kms Year: 2007 VIN: 7AT0GF09X18075786  Under Carriage & Under Bonnet Inspection Comments  General Comments			Seats: Good  Carpets: Good  Panels: Good  Dashboard: Good  Engine Timing Mechanism: Cambelt  Evidence of Cam Belt Replacement: Yes  Replaced At (odometer reading): 106,184  Road Conditions During Test Drive: Dry				
Electrical	Transmission	& Drive	Engine		<b>Tyres</b> (lowest obsidepth)	served tread	
Battery Head lights	Operation Noise	<b>V</b>	Oil level Smoke & fumes	<b>V</b>	Left front Right front		mm
Tail lights	Clutch	•	Performance		Left rear	4	mm
Indicators	CV joints		Noise		Right rear	4	mm
Dashboard warning light:	Wheel bearing	gs 🔽	Cooling System		Spare	Yes	_
Wipers (front & rear)	Wheel balance	e	Coolant condition		Tools		•
Window winder FL	Brakes		Performance		Interior		
Window winder FR	Performance		Radiator / Hoses (visual)		AC Operation	6	
Window winder RL  Window winder RR  Window winder RR		<b>V</b>	Suspension Heater fan				

•

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Reversing camera

**Keys & Locking** 

**Central locking** 

Remote locking

Number of keys

1

Suspension performance

Steering performance

Inspected by: Xinghui Lin

**Shock absorbers** 

Date: 22 Oct 2018

**X** = Fail = Not applicable for this vehicle

Seatbelts

**Turners Certified Key** 

✓ = Pass

Horn