

Turners Certified Imports 50 Point Check

Report ID: 17,757,077

Version:

Created: 13 Dec 2018

Date: 13 Dec 2018

Signature:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED IMPORTED VEHICLES	diagnostic testing undertaken. The ve accredited inspection agency and been	hicle has undergone a thorough co test driven up to 50km/h from cold.	ompliance check by an NZTA
Make: Mazda Model: Axela Year: 2009 Under Carriage & Under General Comments	Body Style: Odometer: 26,230 Kms VIN: 7AT0C13JX18734432 Per Bonnet Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading): Road Conditions During Test Drive:	Timing Chain Not Applicable Dry
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front 7 mm
Tail lights	Clutch	Performance	Left rear 7 mm
Indicators	CV joints	Noise	Right rear 7 mm
Dashboard warning light	wheel bearings	Cooling System	Spare N/A
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail ■ = Not applicable for this vehicle

2

Inspected by: Bobby Zhong

Number of keys

Reversing camera