

## Turners Certified Imports 50 Point Check

Report ID: 17,757,096 Version: 1 Created: 20 Dec 2018

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Suzuki	Body Style:	Wagon
Model:	Landy	Odometer:	94,795 Kms
Year:	2009	VIN:	7AT0GKGHX18681450

Under Carriage & Under Bonnet Inspection Comments

	Seats:	Good	
	Carpets:	Good	
]	Panels:	Good	
	Dashboard:	Good	
	Engine Timing Mechanism:		Timing Chain
]	Evidence of Cam Belt Replacement:		Not Applicable

Dry

Evidence of Cam Belt Replacement:

Replaced At (odometer reading):

Road Conditions During Test Drive:

	-
General	Comments

Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)
Battery	Operation	Oil level	Left front 4.5 mm
Head lights	Noise	Smoke & fumes	Right front 4.5 mm
ail lights	Clutch	Performance	Left rear 5.0 mm
ndicators	CV joints	Noise	Right rear 5.0 mm
ashboard warning lights 🚺	Wheel bearings	Cooling System	Spare Yes
Vipers (front & rear)	Wheel balance	Coolant condition	Tools
Vindow winder FL	Brakes	Performance	Interior
indow winder FR	Performance	Radiator / Hoses (visual)	AC Operation
indow winder RL	Hand Brake		Heater fan
indow winder RR		Suspension	Seatbelts
ear view mirrors	Keys & Locking	Suspension performance	
adio (basic test only)	Central locking	Steering performance	Horn
D (basic test only)	Remote locking	Shock absorbers	<ul> <li>Turners Certified Key</li> <li>✓ = Pass X = Fail</li> <li>● = Not applicable for this vehicle</li> </ul>
eversing camera •	Number of keys 1	Inspected by: Ca Thach	Date: 12 Dec 2018

Signature: .....