

Turners Certified Imports 50 Point Check

 Report ID:
 17,757,272

 Version:
 1

 Created:
 21 Jan 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Subaru	Body Style:	SUV
Model:	Forester	Odometer:	88,901 Kms
Year:	2006	VIN:	7AT0GF17X18094252

Under Carriage & Under Bonnet Inspection Comments

Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
Engine Timi	ng Mechanism:	Cambelt
Evidence of	Cam Belt Benlacement	No

General Comments

Electrical

Evidence of Cam Belt Replacement: Replaced At (odometer reading): Road Conditions During Test Drive: Dry

Battery	•
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	1

Window winder FL

Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Reversing camera

	Operation	
	Noise	
	Clutch	•
	CV joints	
	Wheel bearings	
	Wheel balance	
	Brakes	
	Performance	
	Hand Brake	
	Keys & Locking	
	Central locking	
 	Central locking Remote locking	
•	_	

Transmission & Drive

Engine	Tyres (lowest observed tread depth)
Oil level	Left front 6.0 mm
Smoke & fumes	Right front 6.0 mm
Performance	Left rear 6.0 mm
Noise	Right rear 6.0 mm
Cooling System	Spare Yes
Coolant condition	Tools
Performance	Interior
Radiator / Hoses (visual)	AC Operation
Suspension	Heater fan
	Seatbelts
Suspension performance	Horn
Steering performance Shock absorbers	Turners Certified Key ✓ = Pass ¥ = Fail ● = Not applicable for this vehicle
Inspected by: Mathew Varghese	ie Date: 19 Dec 2018

Name:

Signature: