

Turners Certified Imports 50 Point Check

Report ID: 17,757,697

Version:

Created: 20 Dec 2018

Note: This report is not a warranty

CERT	This rep diagnos accredit	ort is a guide only. Con: tic testing undertaken. ed inspection agency ar	sideration is The vehicl nd been test	s made for ag le has under t driven up to	ge and mileage. Parts gone a thorough co 50km/h from cold.	have not been d mpliance check	ismantled by an NZ
Make:		ly Style: Wagon		Seats:	Good		
	Wingroad Odd 2007 VIN	ometer: 70,190 Kms : 7AT0DH5GX180	18252	Carpets:	Good		
Under Carriage & Under Bonnet Inspection Comments				Panels: Good			
				Dashboard:	Good		
				Engine Timir	ng Mechanism:	Timing Chain	
General Comments				Evidence of Cam Belt Replacement: Not Applicable			
				Replaced At	(odometer reading):		
				Road Condit	ions During Test Drive:	Wet	
Electrica	ı	Transmission & Drive		Engine		Tyres (lowest obse	rved tread
Battery		Operation		Oil level		Left front	5.0
Head ligh	hts	Noise		Smoke & fun	nes	Right front	5.0
Tailliala		Charak		D - "f - "		1 - 6	6.0







