

## Turners Certified Imports 50 Point Check

Report ID: 17,758,159

Version: 1

Created: 27 Dec 2018

Pass X = FailNot applicable for this vehicle

Date: 27 Dec 2018

Signature: .....

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

	ody Style: Hatchback	Seats: Average	
odel: CT200H Od ar: 2013 VI	dometer: 66,138 Kms N: 7AT0B010X18147431	Carpets: Good	
Under Carriage & Under Bonnet Inspection Comments		Panels: Average	
		Dashboard: Good	
		Engine Timing Mechanism:	Timing Chain
General Comments		Evidence of Cam Belt Replacemen	t: Not Applicable
		Replaced At (odometer reading):	
		Road Conditions During Test Drive	e: Wet
ectrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)
ttery	Operation	Oil level	Left front 7
ead lights	Noise	Smoke & fumes	Right front 7
llights	Clutch	Performance	Left rear 7
licators	CV joints	Noise	Right rear 7
shboard warning lights	Wheel bearings	Cooling System	Spare Yes
pers (front & rear)	Wheel balance	Coolant condition	Tools
ndow winder FL	Brakes	Performance	Interior
ndow winder FR	Performance	Radiator / Hoses (visual)	AC Operation
ndow winder RL		Radiator / Hoses (visual)	
ndow winder RR	Hand Brake	Suspension	Heater fan
ar view mirrors	Keys & Locking	Suspension performance	Seatbelts
dio (basic test only)	Central locking	Steering performance	Horn

**Shock absorbers** 

Inspected by: Jason Law

2

Remote locking

Number of keys

CD (basic test only)

Reversing camera