

Turners Certified Imports 50 Point Check

Report ID: 17,759,113

Version:


Created: 21 Jan 2019


Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTI	a cerodi	stic testing undertaken. The ted inspection agency and be	ne vehicle has under oeen test driven up to	rgone a thorough colo 50km/h from cold.	mpliance check k	by an NZ	ŻTA
Make.	Mazda Body Style: SUV		Seats:	Good			
Model.	2013 VIII	N: 7AT0C144X191207	Carpets:	Good			
Under Carriage & Under Bonnet Inspection Comments			Panels:	Panels: Good			
			Dashboard:	Good			
			Engine Timir	ng Mechanism:	Timing Chain		
General (<u>Comments</u>			Cam Belt Replacement: (odometer reading):	Not Applicable		
				tions During Test Drive:	Dry		
Electrical		Transmission & Drive	Engine		Tyres (lowest obserdepth)	ved tread	
Battery		Operation	Oil level		Left front	5.0	mr
Head light	ts	Noise [Smoke & fur	nes	Right front	4.0	mr
Tail lights		Clutch	• Performance		Left rear	3.0	mr









Inspected by: Bobby Zhong Date: 17 Jan 2019

= Not applicable for this vehicle