

## Turners Certified Imports 50 Point Check

Report ID: 17,759,477

Version: 1

Created: 23 Jan 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED IMPORTED VEHICLES	accredited inspe	ng undertaken. ection agency ar	. The vehic nd been tes	tle has unde st driven up t	ergone a the to 50km/h fre	orough co om cold.	impliance check	by an N	ZIA
Make: Mazda  Body Style: Sedan  Model: Atenza  Odometer: 114,665 Kms  Year: 2007  VIN: 7AT0C139X19401347  Under Carriage & Under Bonnet Inspection Comments  General Comments				Seats: Good  Carpets: Good  Panels: Good  Dashboard: Good  Engine Timing Mechanism: Timing Chain  Evidence of Cam Belt Replacement: Not Applicable  Replaced At (odometer reading):  Road Conditions During Test Drive: Wet					
Electrical	Trans	smission & Drive		Engine	itions During	lest Drive:	Tyres (lowest obse	erved tread	
Battery	Opera			Oil level			depth)  Left front	2.5	mm
Head lights	Noise			Smoke & fu	mes		Right front	2.5	mm
Tail lights	Clutch	า	•	Performano	ce		Left rear	2	mm
Indicators	CV joi	nts		Noise			Right rear	2	mm
Dashboard warning lights	Whee	l bearings		Cooling Sy	rstem		Spare	Yes	
Wipers (front & rear)  Window winder FL	Whee	l balance		Coolant cor			Tools	V	
Window winder FR	Brake	es		Performano	ce		Interior		
Window winder RL	Perfor	rmance		Radiator / F	Hoses (visual)		AC Operation		
Window winder RR	Hand	Brake		Suspension	n		Heater fan		
Rear view mirrors	Keys	& Locking		Suspension	n performance		Seatbelts		
Radio (basic test only)	Centra	al locking		Steering pe	erformance		Horn		
i .	<b>4</b>		1	1			I Turmous Coutified !	/ 011	

**Shock absorbers** 

Inspected by: Xinghui Lin

✓ = Pass

**X** = Fail = Not applicable for this vehicle

Date: 23 Jan 2019

Signature: .....

•

1

•

Remote locking

Number of keys

CD (basic test only)

Reversing camera