

Turners Certified Imports 50 Point Check

Report ID: 17,759,682

Version:

Created: 16 Apr 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

IMPORTED VEHICLES	accredited	d inspection agency a	nd been tes	st driven up to	50km/h from	cold.			
Make: Toyota Body Style: Hatchback Model: Vitz Odometer: 50,872 Kms Year: 2009 VIN: 7AT0H63EX19140885 Under Carriage & Under Bonnet Inspection Comments General Comments				Seats: Average Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Replaced At (odometer reading):					
					ions During Test		Wet		
Electrical		Transmission & Drive		Engine			Tyres (lowest observed tread depth)		
Battery		Operation		Oil level	•	1	Left front	7	mm
Head lights		Noise		Smoke & fun	nes		Right front	7	mm
Tail lights		Clutch	•	Performance	<u> </u>		Left rear	7	mm
Indicators		CV joints		Noise	•		Right rear	7	mm
Dashboard warning lights		Wheel bearings		Cooling Sys	tem		Spare	Yes	
Wipers (front & rear)		Wheel balance		Coolant con			Tools	V	
Window winder FL		Brakes		Performance	_		Interior		
Window winder FR		Dorformanco					AC Operation	Ī	
Window winder RL		Performance		Radiator / Ho	Dises (VISUAI)		AC Operation	[
Window winder RR		Hand Brake		Suspension			Heater fan	[
Rear view mirrors		Keys & Locking		Suspension	performance [Seatbelts		

•

Central locking

Remote locking

Number of keys

Radio (basic test only)

CD (basic test only)

Reversing camera

2

Steering performance

Inspected by: Roger King

Shock absorbers

Date: 16 Apr 2019

X = Fail = Not applicable for this vehicle

Horn

Turners Certified Key

✓ = Pass