

Turners Certified Imports 50 Point Check

Report ID: 17,759,800 Version: 1 Created: 12 Apr 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Honda	Body Style:	SUV
Model:	Stepwagon	Odometer:	95,299 Kms
Year:	2008	VIN:	7AT08G87X19314274

Under Carriage & Under Bonnet Inspection Comments 2WD

Engine Timir	ng Mechanism:	Tir	ming Chain	
Dashboard:	Good			
Panels:	Good			
Carpets:	Good			
Seats:	Good			

Wet

General Comments

Not Applicable **Evidence of Cam Belt Replacement:**

Replaced At (odometer reading):

Road Conditions During Test Drive:

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)	
Battery	Operation	Oil level	Left front 7.0 mm	
Head lights	Noise	Smoke & fumes	Right front 7.0 mm	
Tail lights	Clutch	Performance	Left rear 7.0 mm	
Indicators	CV joints	Noise	Right rear 7.0 mm	
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes	
Wipers (front & rear)	Wheel bearingsImage: Comparison of the second s		Tools	
Window winder FL	Bushas	Coolant condition		
Window winder FR	Brakes	Performance	Interior	
	Performance	Radiator / Hoses (visual)	AC Operation	
Window winder RL	Hand Brake		Heater fan	
Window winder RR		Suspension	Seatbelts	
Rear view mirrors	Keys & Locking	Suspension performance		
Radio (basic test only)	Central locking	Steering performance	Horn	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓= PassX= Fail●= Not applicable for this vehicle	
Reversing camera	Number of keys 2	Inspected by: Ca Thach	Date: 11 Apr 2019	

I have read and understood this condition guide.

Name:

Signature: