

Turners Certified Imports 50 Point Check

Report ID: 17,759,837

Version: 1

Created: 01 May 2019

Signature:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

IMPORTED VEHICLES	redited inspection agency and been	test driven up to 50km/h from cold.	mphance check by an NZTA
Make: Subaru	Body Style: Hatchback	Seats: Good	
Model: Impreza Year: 2011	Odometer: 80,402 Kms VIN: 7AT0GF09X19052379	Carpets: Good	
Under Carriage & Under Bonnet Inspection Comments		Panels: Good	
2WD		Dashboard: Good	
		Engine Timing Mechanism:	Cambelt
General Comments		Evidence of Cam Belt Replacement:	No
		Replaced At (odometer reading):	
		Road Conditions During Test Drive:	Dry
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front 7 mm
Tail lights	Clutch	Performance	Left rear 7 mm
Indicators	CV joints	Noise	Right rear 7 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR			
Window winder RL	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RR	Hand Brake	Suspension	Heater fan
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle
Reversing camera •	Number of keys 1	Inspected by: Mathew Varghese	Date: 01 May 2019