

Turners Certified Imports 50 Point Check

 Report ID:
 17,765,412

 Version:
 1

 Created:
 25 Jan 2019

|--|

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

		Seats:GoodCarpets:GoodPanels:GoodDashboard:GoodEngine Timing Mechanism:Evidence of Cam Belt Replacement:Replaced At (odometer reading):Road Conditions During Test Drive:	Cambelt No Wet
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 5 mm
Head lights	Noise	Smoke & fumes	Right front 5 mm
Tail lights	Clutch	Performance	Left rear 6 mm
Indicators	CV joints	Noise	Right rear 5 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL			
Window winder RR	Hand Brake	Suspension	Heater fan
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓= PassX= Fail●= Not applicable for this vehicle
Reversing camera •	Number of keys 2	Inspected by: Jason Law	Date: 25 Jan 2019

Name:

.....