

## **Turners Certified Imports 50 Point Check**

Report ID: 17,765,420 Version: 1 Created: 25 Jan 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Suzuki	Body Style:	Hatchback
Model:	Splash	Odometer:	90,153 Kms
Year:	2010	VIN:	TSMEXB32S00369343

Under Carriage & Under Bonnet Inspection Comments

]	Seats:	Good	
	Carpets:	Good	
]	Panels:	Good	
	Dashboard:	Good	
]	Engine Timir	ng Mechanism: Timin	g Chain

Dry

Not Applicable Evidence of Cam Belt Replacement:

Replaced At (odometer reading):

Road Conditions During Test Drive:

## **General Comments**

Electrical		Transmission & Drive		Engine		<b>Tyres</b> (lowest observed tread depth)		
Battery		Operation		Oil level		Left front	6	mm
Head lights		Noise		Smoke & fumes		Right front	6	mm
ail lights		Clutch [	•	Performance		Left rear	6	mm
ndicators		CV joints		Noise		Right rear	6	mm
ashboard warning light	s 🗹	Wheel bearings		Cooling System		Spare	Yes	
/ipers (front & rear)		Wheel balance		Coolant condition		Tools	V	
/indow winder FL		Brakes		Performance		Interior		
/indow winder FR		Performance		Radiator / Hoses (visual)		AC Operation	Ĩ	
/indow winder RL		Hand Brake		,		Heater fan		
/indow winder RR				Suspension		Seatbelts		
ear view mirrors		Keys & Locking		Suspension performance		Horn		
adio (basic test only)		Central locking		Steering performance				
D (basic test only)		Remote locking		Shock absorbers		<ul> <li>Turners Certified</li> <li>✓ = Pass</li> <li>● = Not applica</li> </ul>	<b>X</b> = Fail	ehicle
leversing camera	•	Number of keys	1	Inspected by: Bobby Zhor	ng		25 Jan 2019	

Signature: .....