

Turners Certified Imports 50 Point Check

Report ID: 17,765,431 Version: 1 Created: 11 Feb 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Mazda	Body Style:	SUV
Model:	MPV	Odometer:	89,155 Kms
Year:	2006	VIN:	7AT0C11EX19108752

Under Carriage & Under Bonnet Inspection Comments

	Seats:	Good	
	Carpets:	Good	
]	Panels:	Good	
	Dashboard:	Good	
	Engine Timing Mechanism:		Timing Chain
]	Evidence of	Cam Belt Replacement [.]	Not Applicable

Dry

General Comments

Evidence of Cam Belt Replacement: Replaced At (odometer reading):

Road Conditions During Test Drive:

lectrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
attery	Operation	Oil level	Left front 8.0 mm
lead lights	Noise	Smoke & fumes	Right front 8.0 mm
ail lights	Clutch	Performance	Left rear 8.0 mr
dicators	CV joints	Noise	Right rear 8.0 mr
ashboard warning lights	Wheel bearings	Cooling System	Spare N/A
ipers (front & rear)	Wheel balance	Coolant condition	Tools
indow winder FL	Brakes	Performance	Interior
indow winder FR	Performance	Radiator / Hoses (visual)	AC Operation
indow winder RL	Hand Brake		Heater fan
ndow winder RR		Suspension	Seatbelts
ar view mirrors	Keys & Locking	Suspension performance	
dio (basic test only)	Central locking	Steering performance	Horn
D (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓= PassX= Fail●= Not applicable for this vehic
eversing camera	Number of keys 2	Inspected by: Ca Thach	Date: 25 Jan 2019

Signature: