

Turners Certified Imports 50 Point Check

Report ID: 17,766,180

Version:

12 Feb 2019 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Toyota **Body Style: Hatchback** Odometer: 94,184 Kms Blade Model: 2007 7AT0H656X18025272 VIN: Year:

Under Carriage & Under Bonnet Inspection Comments

General Comments


Good Seats: Good Carpets: Good Panels: Dashboard: Good


Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading):

Dry **Road Conditions During Test Drive:**

Electrical	
Battery	V
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	

Reversing camera





Inspected by: Mathew Varghese



Date: 04 Feb 2019