

Turners Certified Imports 50 Point Check

Report ID: 17,766,506


Version:


Created: 04 Mar 2019


Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold. Subaru **Body Style: SUV** Make: Good Seats: Odometer: 110,274 Kms Forester Model: Good Carpets: 7AT0GF17X19019896 2008 VIN: Year: Good Panels: **Under Carriage & Under Bonnet Inspection Comments** Dashboard: Good Cambelt **Engine Timing Mechanism:** No **General Comments Evidence of Cam Belt Replacement:** Replaced At (odometer reading): Dry **Road Conditions During Test Drive: Tyres** (lowest observed tread **Transmission & Drive Engine** depth) 7.0 **Battery** Operation Oil level Left front 7.0 **Head lights** Noise Smoke & fumes Right front 2.0 Tail lights Clutch Performance Left rear









Inspected by:	Mathew Varghese	Date:	11 Feb 2019	