

Turners Certified Imports 50 Point Check

Report ID: 17,766,872

Version:


Created: 13 Feb 2019


Note: This report is not a warranty


This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

	TIFIED D VEHICLES	diagnostic accredited	testing undertaken. The dinspection agency and be	e vehicle has under een test driven up to	rgone a thorough co 50km/h from cold.	impliance check	by an NZ	ZTA
Make: Honda Body Style: Sedan Model: Accord Odometer: 75,858 Kms Year: 2005 VIN: 7AT08G13X19100996 Under Carriage & Under Bonnet Inspection Comments			Seats: Carpets: Panels: Dashboard:	Good Good Good				
General Comments				Evidence of Replaced At	ng Mechanism: Cam Belt Replacement: (odometer reading): tions During Test Drive:	Timing Chain Not Applicable Wet		
Electrica	al		Transmission & Drive	Engine		Tyres (lowest observed)	erved tread	
Battery			Operation	Oil level		Left front	4.0	mm
Head lig	hts		Noise	Smoke & fur	mes	Right front	4.0	mm
Tail light	ts		Clutch	• Performance		Left rear	5.0	mm
Indicato	rs		CV joints	Noise		Right rear	5.0	mm

Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Reversing camera •







Inspected by:	Xinghui Lin	Date:	13 Feb 2019

• = Not applicable for this vehicle