

## Turners Certified Imports 50 Point Check

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Volkswagen	Body Style:	Hatchback
Model:	Golf	Odometer:	63,683 Kms
Year:	2006	VIN:	WVWZZZ1KZ6U023579

Under Carriage & Under Bonnet Inspection Comments

Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
Engine Timii	ng Mechanism:	Cambelt
Evidonco of	Cam Bolt Poplacomont	No

**General Comments** 

Evidence of Cam Belt Replacement: Replaced At (odometer reading):

Dry Road Conditions During Test Drive:

Electrical	Transmissi	Transmission & Drive		Engine		<b>Tyres</b> (lowest observed tread depth)		
Battery	Operation			Oil level		Left front	3.0	mm
lead lights	Noise			Smoke & fumes		Right front	3.0	mm
ail lights	Clutch		•	Performance		Left rear	3.0	mm
ndicators	CV joints			Noise		Right rear	3.0	mm
ashboard warning lights	Wheel bear	ings		Cooling System		Spare	Yes	]
/ipers (front & rear)	Wheel bala	nce		Coolant condition		Tools	V	
/indow winder FL	Brakes			Performance		Interior		
indow winder FR	Performanc	ce		Radiator / Hoses (visual)		AC Operation	[	
indow winder RL	Hand Brake				<u> </u>	Heater fan		
indow winder RR				Suspension		Seatbelts		
ear view mirrors	Keys & Loc	king		Suspension performance				
adio (basic test only)	Central lock	king		Steering performance		Horn		
D (basic test only)	Remote loc	king		Shock absorbers		Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle		
eversing camera	Number of	keys	2	Inspected by: Mathew V	arghese		18 Feb 2019	

Name: .....

Signature: .....