

Turners Certified Imports 50 Point Check

Report ID: 17,767,090

Version: 1


Created: 18 Feb 2019


Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or


	diagn accred	ostic testing undertaken. dited inspection agency an	The vehicle has und dependent description of the dependent description of the description of the dependent description of the d	ergone a thorough co to 50km/h from cold.	mpliance check	by an NZ	ZTA
Make: Model: Year: Under (Tiida (Body Style: Hatchback Odometer: 48,291 Kms /IN: 7AT0DH78X1931 net Inspection Comments	Seats: Carpets: Panels: Dashboard	Good Good Good			
<u>Genera</u>	Il Comments		Evidence of Replaced A	Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading): Road Conditions During Test Drive: Dry			
Electrica	al	Transmission & Drive	Engine		Tyres (lowest obserdepth)	rved tread	
Battery		Operation	Oil level		Left front	5.0	mr
Head lig	ghts	Noise	Smoke & fo	umes	Right front	6.0	mı
Tail ligh	ts	Clutch	Performan	ce	Left rear	4.0	mı

Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	





Inspected by: Mathew Varghese



	~	=	Pass X = Fail
•	•	=	Not applicable for this vehicle

Date: 17 Feb 2019