

Turners Certified Imports 50 Point Check

Report ID: 17,767,128 Version: 1 Created: 14 Feb 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Toyota	Body Style:	Hatchback
Model:	Corolla	Odometer:	110,014 Kms
Year:	2007	VIN:	7AT0H607X19030046

Under Carriage & Under Bonnet Inspection Comments

Seats:	Good		
Carpets:	Good		
Panels:	Good		
Dashboard:	Good		
Engine Timi	ng Mechanism:	Timing Chain	

Wet

General Comments

Not Applicable

Evidence of Cam Belt Replacement:

Replaced At (odometer reading):

Road Conditions During Test Drive:

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 3.5 mm
Head lights	Noise	Smoke & fumes	Right front 3.5 mm
Tail lights	Clutch	Performance	Left rear 3 mm
Indicators	CV joints	Noise	Right rear 3 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle
Reversing camera	Number of keys 1	Inspected by: Xinghui Lin	Date: 14 Feb 2019

Name:

Signature: