

Turners Certified Imports 50 Point Check

 Report ID:
 17,767,267

 Version:
 1

 Created:
 19 Feb 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Honda	Body Style:	Hatchback
Model:	FIT	Odometer:	83,746 Kms
Year:	2013	VIN:	7AT08G2YX19004729

Under Carriage & Under Bonnet Inspection Comments

	Seats:	Good		
	Carpets:	Good		
]	Panels:	Good		
	Dashboard:	Good		
	Engine Timir	ng Mechanism:	Timing Chain	

Not Applicable

Dry

Evidence of Cam Belt Replacement:

Replaced At (odometer reading):

Road Conditions During Test Drive:

General Comments

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 4.0 mm
Head lights	Noise	Smoke & fumes	Right front 4.0 mm
Tail lights	Clutch	Performance	Left rear 4.0 mm
Indicators	CV joints	Noise	Right rear 6.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle
Reversing camera •	Number of keys 1	Inspected by: Mathew Varghese	Date: 17 Feb 2019

Name:

Signature: