

Turners Certified Imports 50 Point Check

Report ID: 17,769,125 Version: 1 Created: 24 Apr 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Subaru	Body Style:	Wagon
Model:	Exiga	Odometer:	98,481 Kms
Year:	2008	VIN:	7AT0GF1RX19002597

Under Carriage & Under Bonnet Inspection Comments

Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboar	_{d:} Good	
Engine Ti	ming Mechanism:	Cambelt

No **Evidence of Cam Belt Replacement:** Replaced At (odometer reading):

Dry Road Conditions During Test Drive:

General Comments

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 4.0 m
Head lights	Noise	Smoke & fumes	Right front 4.0 m
ail lights	Clutch	Performance	Left rear 4.0 m
ndicators	CV joints	Noise	Right rear 4.0 m
Dashboard warning lights 🚺	Wheel bearings	Cooling System	Spare Yes
Vipers (front & rear)	Wheel balance	Coolant condition	Tools
Vindow winder FL	Brakes	Performance	Interior
Vindow winder FR	Performance	Radiator / Hoses (visual)	AC Operation
/indow winder RL	Hand Brake		Heater fan
/indow winder RR		Suspension	Seatbelts
ear view mirrors	Keys & Locking	Suspension performance	Horn
adio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓= PassX= Fail●= Not applicable for this vehicle
Reversing camera	Number of keys 1	Inspected by: Bobby Zhong	Date: 26 Mar 2019

Signature: