

2007

Year:

## **Turners Certified Imports 50 Point Check**

Report ID: 17,769,777

Version: 1

Created: 24 May 2019

## Note: This report is not a warranty

7AT08GADX19058133

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Honda Body Style: SUV

Model: Stream Odometer: 98,317 Kms

VIN:

**Under Carriage & Under Bonnet Inspection Comments** 

General Comments
2wd

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism:


Evidence of Cam Belt Replacement:


Not Applicable

Replaced At (odometer reading):


Road Conditions During Test Drive: Wet

Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	





Inspected by: Bobby Zhong



Date: 11 Apr 2019