

Report ID: 17,798,427 Version: 1 Created: 05 Apr 2019

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2010	<b>Registration:</b>	FDC794	Reg Expiry:	06 Jan 2020	Engine	1		.1
WoF Expiry:	29 Nov 2019	Odometer:	174,725 Kms	Good No:	17798427	Oil level	~		
VIN:	MMAJNKB40AD00408	Next Service:	184,000kms	Service Histor	<b>y:</b> No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional c	harge.	Coolant condition	~		1
						Performance	~		
Key:	SSC S	-0	SP SP	-161-	SDR	Radiator / Hoses (visual)	~		<u> </u>
S = scratch	RE	A U			The second	Transmission			
D = dent	S PT SC			15	FILL S	Operation		~	
R = rust PT = paint def				$\prod$		Noise	~	•	
C = crack					PT SC	Clutch	~		
P = pin dent						CV joints	~		
* = decals	SDSC 916			The	ELP SDP	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S D S S S D						Performance			1
		Note: con		may not be disp		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	oftur	
<ul> <li>- 2 x small stone cracks in windscreen, one in middle &amp; the other on left side of windscreen.</li> <li>- Paint clear coat lifting off roof of canopy.</li> </ul>						Tyres (lowest observed tread depth of tyres)           Left front         9.8         mr			
- Screw holes in left & right rear corners of canopy roof.									mm
- Dent in rig	ght rear corner of rear gu	uard, which has b	proken the reflector.			Right front		).2	mm
						Left rear		).2	mm
Conditions During Body Inspection: Dry						Right rear	10.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	inet inspectic	<u>on comments</u>			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
Interior Comments						Operation	~		
Good						Electrical / Accessories			1
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Card					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dachhaa	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
- Gearbox stiff to change from 2nd to 3rd & also changing down from 3rd to 2nd. - Left side catch on rear canopy door is not working.						Window winder RR	~		
		j				Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
						L			
Inspected by: Jason Young Date: 05 Apr 2019									
I have read and understood this condition guide. Name:									