

Basic Vehicle Condition Guide

Report ID: 17,798,946


Version: 1

Created: 13 May 2019

Make: Model: Isuzu D-MAX **Body Style:** Utility Year: 2017 Registration: KLA812 Reg Expiry: 23 Jun 2019 **Odometer:** WoF Expiry: **Good No:** 24 Mar 2020 24,500 Kms 17798946 VIN: MPATFR85JGT003587 Next Service: 24,000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Two small stone cracks in right side of windscreen. Scratches in both right & left side tail light lenses.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Young Date: 06 May 2019

Name:

| | Pass | Fail | N/A | |
|------------------------------|----------------------------------------------|-------|---------------------------------------|--|
| Engine | F 033 | ı alı | IN/ A | |
| Oil level | ~ | | | |
| Smoke & fumes | | | | |
| Performance | <i>V V</i> | | | |
| Noise | • | | | |
| Cooling System | • | | | |
| Coolant condition | ~ | | | |
| Performance | • | | | |
| Radiator / Hoses (visual) | • | | | |
| Transmission | | | | |
| Operation | | | | |
| Noise | ~ | | | |
| Clutch | <i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i> | | | |
| | | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | |
| CV joints | • | | | |
| Wheel bearings | • | | | |
| Brakes | | | | |
| Performance | • | | | |
| Hand Brake | · · | | Ļ | |
| Tyres (lowest observed tread | | | | |
| Left front | | .6 | mm | |
| Right front | 6.0 | | mm | |
| Left rear | 4.1 | | mm | |
| Right rear | 3.5 | | mm | |
| Spare | | Yes | | |
| Suspension | | 1 | | |
| Suspension performance | \(\sigma \) | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | \(\times \) | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | \(\times \) | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |
| | | | | |

Signature: