

Report ID: 17,885,732 Version: 6 Created: 13 Sep 2018

| Make: | Volkswagen | Model: | Crafter | Body Style: | Van | | Pass | Fail | N/A | |
|--|------------------------|------------------|-------------|----------------|-------------|--|-------------|------|-----|--|
| Year: | 2015 | Registration: | JJP850 | Reg Expiry: | 23 Sep 2018 | Engine | | | | |
| WoF Expiry: | 03 Aug 2019 | Odometer: | 162,375 Kms | Good No: | 17885732 | Oil level | ~ | | | |
| VIN: | WV1ZZZ2EZF6005024 | Next Service: | 117235 | Service Histor | V: No | Smoke & fumes | ~ | | | |
| | | | | | - | Performance | - | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | - | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | ling System | | | |
| | | | | | | Coolant condition | | | | |
| | | _ | | | | Performance | ~ | • | | |
| Key: | | -0 | SD SD | | S D R | Radiator / Hoses (visual) | • | | ~ | |
| S = scratch | | | | | | Transmission | | | | |
| D = dent | | | | | | Operation | ~ | | | |
| | | | | | | Noise | ~ | | | |
| PT = paint defect C = crack | | | | | | Clutch | ~ | | | |
| P = pin dent | | | | | | CV joints | ~ | | | |
| * = decals SC Q Q | | | | | | | | | ~ | |
| SC = stone chips | | | | | | Wheel bearings | | | ~ | |
| W = significant scuffs S D S D S D S D R | | | | | | Brakes | | | | |
| | | | | | | Performance | ~ | | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Hand Brake | ~ | | Ļ | |
| Spare tyre missing | | | | | | Tyres (lowest observed tread depth of tyres) | | | 2S) | |
| Stone chips on windscreen Right wing mirror indicator damage | | | | | | Left front 5 | | | mm | |
| Left tail light damage | | | | | | Right front | 4 | 1 | mm | |
| | | | | | | Left rear | 3 | 3 | mm | |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 7 mm | | | |
| | | | | | | Spare No | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | | |
| Coolant overfill and coolant condition fail Unable to carry out hoist and underbody inspection | | | | | | Suspension performance | ~ | | | |
| | any out noist and unde | rbody inspection | I | | | Steering performance | ~ | | | |
| | | | | | | Shock absorbers | | | ~ | |
| | | | | | | Air Conditioning / Heater | | | | |
| | | | | | | Operation | ~ | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | | |
| Seats | Poor | | | | | Head lights | ~ | | | |
| | Average | | | | | Tail lights | ~ | | | |
| Carpets | | | | | | Indicators | ~ | | | |
| Panels | Average | | | | | Dashboard warning lights | | > | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | | |
| | | | | | | Window winder FR | ~ | | | |
| General Comments | | | | | | Window winder RL | | | ~ | |
| Check engine light stays on | | | | | | Window winder RR | | | ~ | |
| | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | | | ~ | |
| | | | | | | Number of keys | 1 | | | |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | ~ | | | |
| Road Conditions During Test Drive: Wet | | | | | | Remote locking | · · | | + | |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | - | | ~ | |
| Evidence of Cam Belt Replacement: No Kms: | | | | | | Reversing camera | | | ~ | |
| | • | | | | | | | | | |
| Inspected by: Ca Thach Date: 13 Sep 2018 | | | | | | | | | | |
| | | | | | | | | | | |
| I have read and understood this condition guide. Name: | | | | | | | | | | |