

Turners Certified Imports 50 Point Check

Report ID: 17,897,712

Version: 3

Created: 05 Oct 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Honda **Body Style: SUV**

Stream Odometer: 42,955 Kms Model:

2005 7AT08GADX18015022 VIN: Year:

Under Carriage & Under Bonnet Inspection Comments


Good Seats: Good Carpets: Good Panels: Dashboard: Good


Cambelt **Engine Timing Mechanism:**

General Comments No **Evidence of Cam Belt Replacement:** Left wing mirror noisy when retracting Replaced At (odometer reading): Dry **Road Conditions During Test Drive: Tyres** (lowest observed tread Electrical **Transmission & Drive Engine** depth)


Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	

Reversing camera





Inspected by: Jason Law



Date: 05 Oct 2018