

Report ID: 17,906,600 Version: 1 21 May 2018 Created:

Signature:

Year: 2,006 Registration: DCR397 Reg Expiry: 06 Oct 2018 WoF Expiry: 04 Aug 2018 Odometer: 123,015 Kms Good No: 17906600 VIN: JMASREA2A6Z000230 Next Service: Service History: No Oil level ✓ Image: Colored Service: Note: This report is not a warranty This report is not a warranty Mode Service: Service History: No Oil level ✓ Image: Colored Service: Note: This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Coolant condition ✓ Image: Colored Service Key: SC SP SP SP SC Coolant condition ✓ Image: Colored Service Coolan			Ma. J. I		De de Cr. J			D .	F . 1	NI/A
Work Expiry: Discrete Discrete <thdis< th=""> Discrete D</thdis<>	Make:						F or a line	Pass	Fail	N/A
VINE JAMSER AJAGODOD 2013 Net Shrupert is and JAGODOD 2014 Service is and JAGO			-							
Note: This report is not a warrany Performance: V This report is a guide only. Consideration is made for age and mileage. Parts have not been dismatted or additional charge. Note: V a full mediation. If made for age and mileage. Parts have not been dismatted or additional charge. V Note: V A full mediation. If made for age and mileage. Parts have not been dismatted or additional charge. V Note: V V Rev: Science for the subscience distance indication is charge. V Note: V				123,015 Kms						<u> </u>
Note: Initial segont is not a warrany diagnostic tooling undertaken the vehicle has been drawn gate to 30 within them odd. The Vehicle recomments is a mechanical mode and the can be avarrage for an avairage f	VIN:	JMASREA2A6Z000230	Next Service:		Service Histor	y: No		-		<u> </u>
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismanted by diagnostic estimation in part to parchase and this can be an anged for an additional charge. Key: Summed to be and this can be an anged for an additional charge. Key: Summed to be and this can be an anged for an additional charge. Part of the summed to be and this can be an anged for an additional charge. Summed to be an additional charge. Part of the summed to be an additional charge. Summed to be an additional charge. Part of the summed to be an additional charge. Summed to be additional charge. Part of the summed to be additional charge. Summed to be additional charge. Part of the summed to be additional charge. Summed to be additional charge. Summed to face. Summed to face. Summed to face. Summed to be additional charge. Summed to face. Summed to be additional charge. Summed to be in data. Summe of the part of the summed to be additional charge. Inderican summed to be additional charge. Summed to be additional charge. Inderican summed to be additional charge. Summed to be additional charge. Summed to be additional charge. Summed to be additional charge. Summed to be additional charge. Summed to be additional charge. Decide additional charge.	Note: This re	port is not a warranty								<u> </u>
Interior Comments Sector description Sector description Sector description Interior Comments Sector description Dry Sector description Dry Sector description Interior Comments Sector description Dry Sector description Dry Sector description Interior Comments Dry Sector description Sector description Dry Sector description Interior Comments Dry Sector description Sector description Dry Sector description Interior Comments Dry Sector description Sector description Dry Sector description Interior Comments Dry Sector description Sector description Dry Sector descr	This report is	a guide only. Conside	eration is made	for age and mileag	e. Parts have not	been dismantled or		~		
Key: Scatch Performance Performance Scatch Performance Performance Performance Pre-paint defect Control Performance Performance Carcols Scatch Performance Performance Performance Performance Performance Performance Scatch Performance Performance Performance Scatch Scatch Performance Performance Performance Scatch Scatch Scatch Performance Performance Performance Scatch Scatch Scatch Scatch Performance Performance Performance Performance Performance Performance Performance							Cooling System			
Key: Source Image: Source I				<u> </u>		J	Coolant condition	~		
South South Badlard Views (Mask) V South SSC SSC Noise V Preprint affect Conditions V Noise V Conditions SSC SSC V SSC V Noise V South SSC SSC SSC V V Noise V V South and totics SSC SSC V SSC V <t< td=""><td>Kow</td><td>SC</td><td>\sim</td><td>SP SP</td><td></td><td>SC</td><td>Performance</td><td>~</td><td></td><td></td></t<>	Kow	SC	\sim	SP SP		SC	Performance	~		
D = dent R = rusit Framission P = paint defect Corack C = cack P = pind dent S = stone chips S Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram S = stone chips Note: some defects & blemishes may not be displayed in the diagram Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram S = stone chips Note: some defects & blemishes may not be displayed in the diagram Under Carriage & Under Bonnet Inspection: Dry Under Carriage & Under Bonnet Inspection Comments Suspension Average condition. Suspension Sets Good Image: Some defects Drate for Comments Suspension Sets Good Image: Some defects Sets Good Image: Some defects Dashboard Good Image: Some defects Drives ok	· ·		$\overline{(0)}$		5(O)-		Radiator / Hoses (visual)	~		
R=ruit defect SS Operation Image: Charles of the section of the section is a sectin a sectin a section is a section is a section is a sec						A I	Transmission			
Interior Comments Server Allos and Allos Aborders Allow and Allow and Allow and Allos Aborders Allow and Allow	R = rust	s sc			10	HIL/S	Operation	~		
P - pin dent	PT = paint def	ect NP	1				Noise	~		
* = decals SC = store chips W = significant south SC = store chips W	C = crack						Clutch			~
Construction Section Section </td <td>P = pin dent</td> <td>HP</td> <td></td> <td></td> <td></td> <td>2414</td> <td>CV joints</td> <td>~</td> <td></td> <td></td>	P = pin dent	HP				2414	CV joints	~		
W = significant scuffs S S W SC Performance V Index Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Screw holes in dash. Stereo needs code. Courtesy lamp lens missing RF door. Hand Brake V Index Index V Index V Index Index Index Index Index <t< td=""><td></td><td></td><td></td><td></td><td>10</td><td>ED S</td><td>Wheel bearings</td><td>V</td><td></td><td></td></t<>					10	ED S	Wheel bearings	V		
Sc Sc W Sc Performance V I Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Hand Brake V I Suntan lotion damage on paints. Stonchips on windscreen. Centre lower section missing from front bumper. Hand Brake V I Screw holes in dash. Storechips on windscreen. Centre lower section missing from front bumper. Left front 4 mm Right front 4 mm Right front 4 mm Right front 6 mm Spree Yes Spree Yes Under Carriage & Under Bonnet Inspection Comments Suspension performance V I I Neerage condition. Suspension performance V I I I Setat Good V I I I I I Panels Good I I I I I I I Dashboard Good I I I I I I I			$\mathcal{O}(\mathcal{O})$		202	×	Brakes			
Dot in spectron inspection damage on pairs. Score/lips on windscreen. Center lower section missing from from bumpers. Screw holes in dash. Stereo needs code. Courtesy lamp lens missing RF door. Tyres (lowest observed tread depth of tyres). Screw holes in dash. Stereo needs code. Courtesy lamp lens missing RF door. Left front 4 mm Right front 4 mm Right front 4 mm Right front 6 mm Spare Yes Stepension Under Carriage & Under Bonnet Inspection: Dry Suspension performance V 1 Suspension performance V 1	w – signincan	SC		S SC		SC	Performance	~		
Suntan lotion damage on paint. Stonechips on windscreen. Center lower section missing from front bumper.	Body Inc	paction Comments	Note: som	ne defects & blemishe	es may not be disp	layed in the diagram	Hand Brake	~		
Screw holes in dash. Stereo needs code. Courtesy lamp lens missing RF door. Left front 4 mm Night front 6 mm Right rear 6 mm Under Carriage & Under Bonnet Inspection Comments Spare Ves Average condition. Suspension performance 1 1 Stagension Ves Suspension performance 1 1 Interior Comments Suspension performance 1 1 1 Seats Good Indicators 1 1 1 Seats Good Ves 1 1 1 Panels Good Ves 1 1 1 Dashboard Good Ves 1 1 1 Drives ok. Good Ves 1 1 1 1 Drives ok. Fail lights V 1 1 1 1 Rear view mirrors V 1 1 1 1 1 1 Drives				dscreen Center Iowe	r section missing f	rom front humper	Tyres (lowest observed tread depth of tyres)			
Right front 4 mm Left rear 6 mm Left rear 6 mm Noted Carriage & Under Bonnet Inspection Comments Suspension Suspension Average condition. Suspension performance 4 1 Suspension performance 4 1 1 Suspension performance 4 1 1 Steering performance 1 1 1 1 Steering performance 1 1 1 1 <td colspan="5"></td> <td colspan="3">Left front 4 mi</td> <td>mm</td>						Left front 4 mi			mm	
Conditions During Body Inspection: Dry Iter rear 6 mm Nurage condition. Spare Yes Suspension Suspension Indicators I							Right front			mm
Conditions During Body Inspection: Dry Right rear 6 mm Spare Spare Yes Suspension Suspension performance / 1 Suspension performance / 1 1 Stearing performance / 1 1 Stearing performance / 1 1 Interior Comments Seats Good / 1 Seats Good 1 1 1 Panels Good / 1 1 Dashboard Good / 1 1 Dirives ok. Good / 1 1 General Comments / / 1 1 Dirives ok. Good / 1 1 Birtono Winder RI / 1 1 1 Dirives ok. Fertical / Accessories / 1 1 Birtono Winder RI / 1 1 1 Dirives ok. Good 1 1 1 Birtono Winder RI /										
Under Carriage & Under Bonnet Inspection Comments Spare yes Average condition. Suspension Suspension performance V 1 Suspension performance V 1 1 Interior Comments V 1 1 Seats Good V 1 1 Carpets Good V 1 1 Dashboard Good V 1 1 General Comments V 1 1 1 General Comments V 1 1 1 Drives ok. Good V 1 1 Badi Conditions During Test Drive: Dry V 1 1 Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 113,100 Xes 1	Conditions During Rody Inspection:									
Under Carriage & Under Bonnet Inspection Comments Average condition. Suspension Average condition. Suspension performance ✓	Conditions During Body inspection: Dry						-	-		
Average condition. Suspension performance ✓ <td colspan="6">Under Carriage & Under Bonnet Inspection Comments</td> <td colspan="3">1 105</td> <td></td>	Under Carriage & Under Bonnet Inspection Comments						1 105			
Interior Comments Image: Control of C		-	·				•	~		
Shock absorbers ✓ I Interior Comments Operation ✓ I Seats Good ✓ I Carpets Good ✓ I Panels Good ✓ I Dashboard Good ✓ I Dashboard Good ✓ I Dashboard Good ✓ I Mindow winder FL ✓ I I Mindow winder FL ✓ I I Window winder FL ✓ I I Window winder FL ✓ I I Drives ok. Window winder RL ✓ I Rear view mirrors ✓ I I Radio (basic test only) I ✓ I Rado conditions During Test Drive: Dry I I Engine Timing Mechanism: Cambelt Kms: 113,100 I I										<u> </u>
Interior Comments Air Conditioning / Heater Seats Good Indicators ories Carpets Good Indicators I Panels Good Indicators I I Dashboard Good Indicators I I Dashboard Good Indicators I I Dashboard Good Indicators I I Mindow winder FL I I I I Divies ok. Window winder RR I I I Rear view mirrors I I I I I Rear view mirrors I I I I I I Road Conditions During Test Drive: Dry Dry Image I I I I Engine Timing Mechanism: Cambelt Yes Kms: 113,100 Image I I I										
Interior Comments Operation ✓ I Seats Good I I Carpets Good Tail lights ✓ I Panels Good Indicators ✓ I Dashboard Good I I I Mindow winder FL ✓ I I I Operation ✓ I I I I I Dashboard Good V ✓ I								V		
Interior Comments Electrical / Accessories Seats Good I Carpets Good I Panels Good I Dashboard Good I Dashboard Good I General Comments V I Drives ok. V I Rear view mirrors V I Road Conditions During Test Drive: Dry I Engine Timing Mechanism: Cambelt Kms: 113,100 I V Reversing camera V I V V										
Seats Good Image: Seats in the search of the search o	Interior Comments									
Seats Good Tail lights V I Panels Good Indicators V I Dashboard Good Indicators V I Dashboard Good Vipers (front & rear) V I Window winder FL V I I Vindow winder FR V I I Drives ok. Window winder RR V I Numdow winder RR V I I Rear view mirrors V I I Radio (basic test only) V V I Road Conditions During Test Drive: Dry Central locking V I Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 113,100 Reversing camera V I	Good									
Carpets Good Indicators ✓ Indicators Panels Good Dashboard warning lights ✓ Indicators Dashboard Good Vindow winder FL ✓ Indicators General Comments ✓ Indicators ✓ Indicators Drives ok. Mindow winder FR ✓ ✓ Indicators Window winder RR ✓ ✓ Indicators ✓ Indicators Rear view mirrors ✓ ✓ ✓ Indicators ✓ Indicators Road Conditions During Test Drive: Dry Indicators ✓ ✓ Indicators ✓ Indicators Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 113,100 Indicators ✓ Indicators ✓ Indicators Rearrise camera V ✓ ✓ ✓ ✓ ✓ Indicators General Comments F ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓	Seats						-			
Panels Good Dashboard warning lights ✓ Image: Comment set Drive: Drives ok. Good Vindow winder FL ✓ Image: Comment set Drive: Drives ok. Vindow winder RR ✓ Image: Comment set Drive: Vindow winder RR ✓ Image: Comment set Drive: Road Conditions During Test Drive: Dry Central locking ✓ Image: Comment set Drive: Vindow Vindow Image: Comment set Drive: Vindow Image: Comment set Drive: Vindow Vindow Image: Comment set Drive: Vindow Image: Comment set Drive: Vindow Vindow <td>Carpets</td> <td>Good</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Carpets	Good								
Panels Gashboard Gashboard warning lights V I Dashboard Good Wipers (front & rear) V I Mindow winder FL V I I Window winder FR V I I Window winder RR V I I Window winder RR V I I Window winder RR V I I Rear view mirrors V I I Radio (basic test only) I V I Image: Comments Drives ok. Image: Comments V Image: Comments Drives ok. Window winder RR V Image: Comments Image: Comments Image: Comments Drives ok. Window winder RR V Image: Comments Image: Comments Image: Comments Image: Comments Image: Comments Read Conditions During Test Drive: Dry Image: Comments Image: Comments </td <td></td> <td>Good</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td><u> </u></td>		Good								<u> </u>
Dashboard Window winder FL ✓ </td <td>Panels</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Panels									
General Comments Vindow winder FL V I General Comments Vindow winder FR V I Drives ok. Window winder RR V I Rear view mirrors V I I Radio (basic test only) V I I CD (basic test only) V V I Number of keys 2 I I Engine Timing Mechanism: Cambelt Sat. Nav. (basic test only) V I Evidence of Cam Belt Replacement: Yes Kms: 113,100 I V I	Dashhoa	Good Good					•	~		<u> </u>
General Comments Window winder RL Image: Comments Drives ok. Window winder RR Image: Comments Window winder RR Image: Comments Image: Comments Rear view mirrors Image: Comments Image: Comments Radio (basic test only) Image: Comments Image: Comments Road Conditions During Test Drive: Dry Image: Comments Engine Timing Mechanism: Cambelt Kms: 113,100 Evidence of Cam Belt Replacement: Yes Kms: 113,100							Window winder FL	~		
Drives ok. Drives ok. Drives ok. Window winder RR Rear view mirrors Rear view mirrors CD (basic test only) CD (basic test onl							Window winder FR	~		
Rear view mirrors V I I Radio (basic test only) V V I Road Conditions During Test Drive: Dry Central locking V I Engine Timing Mechanism: Cambelt Kms: 113,100 Sat. Nav. (basic test only) I V Evidence of Cam Belt Replacement: Yes Kms: 113,100 Reversing camera I V		<u>comments</u>					Window winder RL	~		
Radio (basic test only) Image: Constant on the second of the second	Drives ok.						Window winder RR	~		
CD (basic test only) I I I Road Conditions During Test Drive: Dry Dry Central locking I I Engine Timing Mechanism: Cambelt Kms: 113,100 Sat. Nav. (basic test only) I I I Evidence of Cam Belt Replacement: Yes Kms: 113,100 I I I							Rear view mirrors	~		
Number of keys 2 Road Conditions During Test Drive: Dry Central locking ✓ Engine Timing Mechanism: Cambelt Remote locking ✓ Evidence of Cam Belt Replacement: Yes Kms: 113,100 Reversing camera ✓ ✓ ✓							Radio (basic test only)		~	
Road Conditions During Test Drive: Dry Central locking Image: Central locking <thimage: central="" locking<="" th=""> Image: Central l</thimage:>							CD (basic test only)		~	
Initial conductors builting rescondence of Cam Belt Replacement: Yes Kms: 113,100							Number of keys	2		•
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 113,100	Road Con	ditions Durina Test	t Drive:	Dry			Central locking	~		
Evidence of Cam Belt Replacement: Yes Kms: 113,100 Reversing camera Image: Construction of Camera		-		- ' J			Remote locking	~		
Evidence of Cam Belt Replacement: Yes Kms: 113,100 Reversing camera V	Engine Ti	ming Mechanism:	Cambelt	t						~
	Evidence	of Cam Belt Replac	ement: Y	es	Kms: 11	3,100				
Inspected by: Roger King Date: 21 May 2018	[1		<u> </u>
	Inspecte	d by: Roger King					Date: 21 May 20	18		

I have read and understood this condition guide.

Name: