

Turners Certified Imports 50 Point Check

Report ID: 17,931,868

Version:

Created: 05 Oct 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold


IMPORTED VEHICLES		est driver up to sokin/ir from cold.	
Model: Avensis O	ody Style: Wagon dometer: 96,053 Kms N: 7AT0H63MX18038361 et Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good	
		Engine Timing Mechanism:	Timing Chain
General Comments		Evidence of Cam Belt Replacement	: Not Applicable
		Replaced At (odometer reading): Road Conditions During Test Drive	. Wet
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 4 mi
Head lights	Noise	Smoke & fumes	Right front 4 mi
Tail lights	Clutch	Performance	Left rear 5 mi
Indicators	CV joints	Noise	Right rear 5 mi
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation

Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	

Window winder RL

Reversing camera

Performance Hand Brake	
Keys & Locking	
Central locking	
Remote locking	
Number of keys	2



Inspected by: Jason Law

Date: 05 Oct 2018

X = Fail