

Turners Certified Imports 50 Point Check

Report ID: 17,955,993

Version:

Created: 19 Mar 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Toyota **Body Style: Hatchback** Odometer: 90,687 Kms Vitz Model: 2007 7AT0H63EX19094259 VIN: Year:

Under Carriage & Under Bonnet Inspection Comments Tidy.

General Comments

Nice little hatch.


Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good


Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading):

Road Conditions During Test Drive:

Dry

Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	V
Rear view mirrors	V
Radio (basic test only)	
CD (basic test only)	
Reversing camera	•







Inspected by:	Daryll Timms	Date:	19 Mar 2019	

= Not applicable for this vehicle