

## **Turners Certified Imports 50 Point Check**

Report ID: 17,956,150

Version: 1

20 Mar 2019 Created:

## **Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Honda Make: **Body Style: Sedan** Odometer: 20,621 Kms Inspire Model: 7AT08G0TX19200410 2009 VIN: Year:

**Under Carriage & Under Bonnet Inspection Comments** Tidy.

**General Comments** 


Nice tidy sedan.


Good Seats: Good Carpets: Good Panels: Dashboard: Good


Timing Chain **Engine Timing Mechanism:** Not Applicable

**Evidence of Cam Belt Replacement:** Replaced At (odometer reading): Dry **Road Conditions During Test Drive: Tyres** (lowest observed tread **Engine** depth)

**Electrical Battery Head lights** Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Reversing camera







Date: 20 Mar 2019